SALTASH NEIGHBOURHOOD DEVELOPMENT PLAN

Sites with potential to encourage and enable upgrading and improvement to standard more appropriate to modern needs.

INDICATORS: Any or all of the following:

- narrow fairways,
- poor road surfacing condition
- inadequate parking and manoeuvring,
- inadequate storage,
- inflexible layouts for expansion,
- poor lighting,
- life-expired buildings,
- poor environment,
- higher levels of vacancy,
- poor signage,
- derelict vehicles and equipment.

POTENTIAL SITES:

- Forge Lane
- Moorlands Lane
- Gilston Road

LOCATION Forge Lane	narrow fairways,	poor road surfacing condition	inadequate parking and maneuvering,	 inflexible layouts for expansion, 	life-expired buildings,	poor lighting,	poor environment,	higher levels of vacancy,	poor signage,	derelict vehicles and equipment.
Forge Lane	✓		√				✓		✓	
Moorlands Lane	√	√		√		√				
Gilston Road / Brunel Road	√		√	√						